SOUTH LAKELAND DISTRICT COUNCIL.

NEIHBOURHOOD SERVICES

CONTRACTS GROUP.

BROUGHTON PARISH ANNUAL PLAYAREA INSPECTION REPORT

DATE OF INSPECTION. 22.03.21

EQUIPMENT	COMMENTS Risk As	sessment	ACTION REQUIRED.
1 Junior Unit	Some rust appearing to brackets on framework Low		Treat the rust & paint over
2 Flat Swing	Wear appearing to the brach chain links Low		Prepare to replace the branch chains
3 Cradle Swing	Corroded nuts to underside of seats Low		Replace corroded nuts
4 Embankment Slide	Okay	Low	
5 Spring Horse	Okay	Low	
6 Rocking Rocket	Okay	Low	
7 Low Rotator	Okay	Low	
8 Seesaw	Okay	Low	
9 Aerial Runway	Exposed concrete. Exposed stones to ground platform plank was free to lift off		Cover concrete/turf Remove stones Repaired at inspection
10 Surfboard	Okay	Low	
11 Roundabout	Okay	Low	
Miscallaneous	Gates, Fencing, Bins	Small area of decay to seat end	
Safety Surfaces	All Okay		
	-		

Inspection carried out by Peter Clarke. Qualifications.

BTEC Level 3 Playground Operation & Inspection.